



Pioneer Sand ESD
Peter Thorpe to: Theresa.Pepe

04/12/2010 02:15 PM

Theresa,

I have attached a draft copy of the Pioneer Sand ESD for your review. The two main reasons for this ESD are include ICs are part of the remedy and to clarify the performance monitoring standards for the cap. The ROD didn't mention ICs and didn't state what the standards would be for judging a functioning vs. non-functioning cap. The purpose of this ESD is clarify those topics. Please let me know if you have any questions.



ESD for Pioneer Sand 041210 draft.doc

Pete Thorpe, PG
Remedial Project Manager
U.S. Environmental Protection Agency, Region 4
Superfund Division
Phone: (404) 562-9688
Fax: (404) 562-8896
Thorpe.Peter@epa.gov